

10ft Extension
Cord



Blk
Wht
Gn

10 AMP
Fuse

Ground / lug

Neutral
Side
Silver
Screws

Gold
Screws

Break
Tab
Off

1 2

3 4

5 6

7 8

Power supply

Sensor

Heat

Cool

Stc-1000

